

Reservoir Survey

Performed by: Regis Bouchard

Date: 21-Jul-2017 **Time:** 1:00 – 2:00 PM

Weather: Partly cloudy with some showers, 19 °C

Surveyed River Area: From Muskrat Falls Site to Gull Island Site


Comments

On the South bank, there is no new slope movement. Some erosion was notified below and over el 21m. Pictures from 1967 to 2002 (T: drive folder) are from South Bank. Pictures from 2003 to 2031 are from the North Bank.

Pay attention to picture 2015 below showing the Lower Brook where no sediment are visible.



Downstream Lower Brook, following pictures show few erosion at the bottom of the slope between KM 49 to 46. Pictures below show what I talking about.





The wind was from east today, no wave effect, so erosion process is low today. Water is visible at the surface of the upper plateau over the slope at KM 47.5.



The transmission lines are near the pond.

For more pictures please check the link below:

T:\Site Construction\6.0 Monitoring\Helicopter Photos\Regis pictures 21-Jul-2017