

Reservoir Survey

Performed by: Mohammad Ansari

Date: 10-Jul-2017

Weather: Cloudy, 19 °C

Surveyed River Area: From Muskrat Falls Site to Gull Island Site

Comments

Most slopes are covered with trees but some sedimentation was observed. Some active erosion along the banks could be observed as trees were falling along the edges. Sedimentation was observed at the toe of all actively eroding areas.



Figure 1: Sedimentation between 67 to 68 Km, RightBank



Figure 2: Sedimentation in the South Bank, 89 km



Figure 3: Steep slopes with no green cover and some sedimentation, 48km North Bank

For more pictures please check the link below:

T:\Site Construction\6.0 Monitoring\Reservoir Survey\10-Jul-2017