

## Reservoir Survey

**Performed by:** Regis Bouchard

**Date:** 18-Jul-2017      **Time:** 1:00 – 2:00 PM

**Weather:** Sunny 20 °C

**Surveyed River Area:** From Muskrat Falls Site to Gull Island Site

## Comments

There is surface sliding ( small) at km 83. Some erosion at the bottom of the slope at 47 to 49 related with remoulded material and wave effect.



**Figure 1: Surface sliding at Km 83, South Bank**



**Figure 2: Some erosion between 47 to 49 km, North Bank**



**Figure 3: Some erosion between 67 and 68 Km South Bank**

For more pictures please check the link below:

T:\Site Construction\6.0 Monitoring\Helicopter Photos\Regis pictures 18-Jul-2017